




ADVISORY LEVEL: EXTREME URGENCY
DESCRIPTION: FUEL PUMP LOOSE CONNECTION
ENGINE TYPE: R2800 and R3600
Action: Establish your pump type.
Don't start engine under any circumstance.
Contact Factory.


ADVISORY DATE: 30th Aug. 2012



STEP 1:

Does your fuel pump look like the one on the left?


If it does continues to step 2



STEP 2:

Tug on the brass fitting

Goto Step 3



STEP 3:

If the fitting comes out or feels loose do not under any circumstance run the engine.

Contact Rotec Support Immediately:

Paul Chernikeeff

Email: paul@rotecaerosport.com

